

Rectification

- DIRECTIONS FOR USE ON REVERSE**

Farécla™

SMART REPAIR POLISHING

For best results follow these recommended steps:

- Apply a small amount of SMART Repair Compound to the surface, smear with the 3" Compounding Foam and start to compound with the SMART 3" Polishing Machine, keeping the foam flat on the surface.
- Continue until the desired finish is achieved.
- Buff off any residue with a Farécla Finishing Cloth.
- On darker colours a second step may occasionally be necessary. Apply a small amount of the SMART Repair Compound and lightly polish using the black SMART 3" Polishing Foam.
- This system is designed to be used totally dry - the addition of water should not be required.

Product Tips:

- For the 3" Polishing Machine air supply requirements are 90 PSI (6 bar) maximum pressure, air volume 4 cubic feet per minute minimum.
- The 3" foams should be cleaned regularly by rinsing in water.
- SMART Compound should be used sparingly - too much product is unnecessary and can make its application appear greasy.
- If desired after compounding, Black Top Hand Glaze can be used to blend in surrounding areas.

Ideal System For:

- Refurbishment centres who remove small dirt nibs
- Import centres
- Large bodyshops that employ SMART technology
- SMART repair franchises

PRODUCT	CODE	CTN QTY
SMART Repair Polishing Kit	SMT-PKIT	1
SMART Repair Compound 500ml	SMT-500	12
Advanced G Mop Compounding Foam 3" 5-pack	SMT-CF	6
Advanced G Mop Polishing Foam 3" 5-pack	SMT-PF	6
Black Top Hand Glaze 500ml	BT-500	12
Advanced GMop Finishing Cloth 3-pack	FC-3	12